
MC transmission [a.u.]
1.0
0.5
0.0
Ringdown #7
Ringdown #6
Ringdown #4
Ringdown #5
Ringdown #9
Ringdown #8
Ringdown #1
Ringdown #3
Ringdown #2
Ringdown #10
100x Fit residuals
5
2
0
-2
-50
0
50
100
150
200
Time [μs]