



Stanford Research Systems

1290C Reamwood Ave, Sunnyvale, CA 94089
Phone: 408-744-9040 FAX: 408-744-9049
email: info@thinkSRS.com Web: www.thinkSRS.com

Instrument Service Report

Date: 21 Aug 2014

Model: SR785

Serial Number: 46795

Technician: T. Nguyen

Reason For Return:

- 1, scrambled screen
- 2, upgrade floppy to USB drive
3. noisy channel 2

Repairs Performed:

Replaced the CRT. Replaced the Floppy drive (defective) with a USB drive.

Unit calibrated.