



Someone thought it a good idea to block the drains on the building site to the North of the 40m.



This lead to a little bit of moisture entering the control room...



...and along the E/W arm.



At some points the water stretched to the other side of the beam tube.





A very helpful man from Physical Plant arrived to unblock the drains whilst we attacked the water inside with his Shop-Vac.