

Vaccum Temperature Inloop Sensor
Heater got shut down abruptly

At around 15:20:25 Aug 16, 2019 PDT the heater shutdown
leading to temperature decay

