

# HAM7 - Air Purge valve for H1 and L1

A modification on documents D1900114 and D1900116 is going to be conducted, and the changes will be modified by Don, as soon as he has the time. This new change is due to the necessity of one port, for the Air Purge valve. Squeezer Tip-Tilts located on D6 (1C1 and 1C2) will change their location to D8, which is located at the top of the chamber. D8 will be a 12-dB25 system Flange.

