









# Coil driver actuation breakdown during lock acquisition [ALS lock from t=20s]

ETMX ( $R_{fast} = 2.25k\Omega$ )



ETMY ( $R_{fast} = 400\Omega$ )



0 5 10 15 20 25 30 35  
Time [s]

0 5 10 15 20 25 30 35  
Time [s]